

Yellow Jacket Drilling Services
 Valued Client
 POB 801
 Gilbert, Arizona 85299

 Project: Drinking Water
 Project Number: HAMP 13-0111 AZ 8/8/13

 Reported:
 08/15/13 15:32

Analyte

DRAFT: Hamp Well #2 (Z1,006) (3080870-01) Drinking Water (Grab) Sampled: 08/08/13 12:00 Received: 08/09/13 13:43

Analyte	Result	PQL	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
---------	--------	-----	-------	----------	-------	----------	----------	--------	-------

Legend Technical Services of Arizona, Inc.

DRAFT: Total Metals

Analyte	Result	PQL	Units	Dilution	Batch	Prepared	Analyzed	Method
Arsenic	0.0029	0.0010	mg/L	1	B3H0290	08/09/13 17:15	08/12/13 15:21	EPA 200.8

Sample Condition Upon Receipt:

 Temperature: 2.00 C
 All samples were received in acceptable condition unless noted otherwise in the case narrative.

Case Narrative:

Holding Times: All holding times were met unless otherwise qualified.

QA/QC Criteria: All analyses met method requirements unless otherwise qualified.

Accreditations: AZ(PHX)0004, AZ(TUC)0004, AIHA#102982, CDC ELITE Member.

Accreditation is applicable only to the test methods specified on each scope of accreditation held by LEGEND.

Comments: There were no problems encountered during the processing of the samples, unless otherwise noted. All samples were analyzed on a "wet" basis unless designated as "dry weight".

Sample was turbid resulting in apparent color. In order to record the true color, the sample was centrifuged at 4500 rpm for 10 minutes. This resulted in a pellet at the bottom of the sample. The supernatant was poured off and the true color was taken from this portion of the sample. 8/15/13 CL

Notes and Definitions

DRAFT REPORT

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

DATA SUBJECT TO CHANGE

Phone Number: (602) 324-6100

Page 1 of 9

ED_005149_00023175-00001